

Work Order ID 150206

Wednesday, August 24, 2016 11:26:42 AM

150206

Page 1

Item ID: D412-666-011 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Gross Weight Towing Adapter
 Start Date: 8/18/2016 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 8/24/2016 Req'd Qty: 1.00 ***1*** Customer:
 Reference:

Approvals: Process Plan: DAS 21 9-89 Date: AUG 25 2016 Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN D412-666	Rev C1	<u>DAS 6 9-89</u>	SEP 16 2016			<u>DAS 21 9-89</u>		<u>16-09-10</u>	
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefile & type labels per PPP412-666-011		CHG 004						
110	Pick Kit	0.00							
110									
Packaging	Memo	0.00							
Packaging									
120	QC4- 100% Inspect kits for completeness	0.00							
120									
QC	Memo	0.00							
Quality Control									

DAS 27 9-89
SEP 22 2016


DAS 6 9-89
SEP 19 2016

DAS 27 9-89
SEP 22 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Work Order ID 150206***150206***

Page 2

Wednesday, August 24, 2016 11:26:42 AM

Item ID: D412-666-011**Accept*****N900040100*****Setup Start*****NS1*****Revision ID:****Stop*****NS2*****Item Name:** Gross Weight Towing Adapter**Start Date:** 8/18/2016 **Start Qty:** 1.00***1*****Cust Item ID:****Required Date:** 8/24/2016 **Req'd Qty:** 1.00***1*****Customer:****Reference:****Approvals:****Process Plan:** _____**Date:** _____**Tooling:** _____**Date:** _____**Run Start*****NR1*****QC:** _____**Date:** _____**SPC (Y/N):** _____**Date:** _____**Stop*****NR2*****Sequence ID/
Work Center ID****Operation
Description****Set Up/
Run Hours****Tool ID****Tool #****Plan
Code****Accept
Qty****Reject
Qty****Reject
Number****Insp.
Stamp**

130

0.00

130

Packaging

Packaging

Memo

0.00

Identify and pack for shipping as per PPP D412-666-011
Location :FG023DAS
27
9-89
SEP 22 2016

140

0.00

140

QC21- Final Inspection - Work Order Release

QC

Memo

0.02

Quality Control

DAS
21
9-89

SEP 22 2016

DAS
21
9-89

SEP 22 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐								
Misidentified	☐	Past Due	☐	OTHER :							

Picklist Print

Wednesday, August 24, 2016 11:26:41 AM

Page 1

Work Order ID: 150206

150206

Parent Item: D412-666-011

D412-666-011

Parent Item Name: Gross Weight Towing Adapter

Start Date: 8/18/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:B Added GHG 002 NG 02-03-06
IPP Rev:C As per Rev C JLM 07-09-07 Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN6-15A *AN6-15A* Bolt		Purchased	No			110	Each	27.0000	4	4			PC
					<u>Location</u>			<u>Loc Qty</u>					
					ST334			27					
					m134867			27		4			
AN6-45A *AN6-45A* Bolt		Purchased	No			110	Each	22.0000	4	4			PC
					<u>Location</u>			<u>Loc Qty</u>					
					over008			15					
					M132677			15					
					ST333			7					
					M127832			7		4			
D2888 *D2888* Lug		Manufactured	No			110	Each	1.0000	2	2			PC
					<u>Location</u>			<u>Loc Qty</u>					
					ST527			1					
					120184			1					

SEP 14 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By _____	
								Lead hand / Supervisor Approval Verification _____	
								QC / QA Coordinator Approval _____	

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐								
Misidentified	☐	Past Due	☐	OTHER : _____							

Picklist Print

Wednesday, August 24, 2016 11:26:41 AM

Page 2

Work Order ID: 150206

150206

Parent Item: D412-666-011

D412-666-011

Parent Item Name: Gross Weight Towing Adapter

Start Date: 8/18/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

MS21042L6

Purchased

No

110

Each

166.0000

4

4

MS21042L6

Nut

**

PC

DAS
6
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST303

166

m133938

6

m134955

50

m135058

60

m135442

50

4

NAS1149D0663J

Purchased

No

110

Each

982.0000

8

8

NAS1149D0663.J

Washer

**

PC

DAS
6
9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

ST260

227

M131618

227

ST260a

600

M135464

600

ST263

150

M135135

150

ST269

5

M126334

5

4

SEP 19 2016

Wednesday, August 24, 2016 11:26:41 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : _____							

1.0 APPLICABILITY:

GROSS WEIGHT TOWING KIT D412-666-011 MAY BE INSTALLED ON DART D205-634-XXX OR D204-635-XXX OR D412-742-XXX SKIDTUBES INSTALLED ON 412 AIRCRAFT TO ALLOW GROUND HANDLING AT GROSS WEIGHT IN ACCORDANCE WITH BELL SERVICE INSTRUCTION BHT-412-SI-58. IT IS ALSO ACCEPTABLE TO INSTALL THIS KIT ON 204/205/210/212 AIRCRAFT EQUIPPED WITH DART SKIDTUBES IN ORDER TO PRESERVE THE LIFE OF THE AFT CROSSTUBES. THIS KIT CONTAINS ENOUGH PARTS TO INSTALL D2888 LUGS ON BOTH SKIDTUBES.

2.0 PARTS LIST:

QTY -011	PART	DESCRIPTION
X	D412-666-011	GROSS WEIGHT TOWING KIT
2	D2888	LUG
4	AN6-15A	BOLT
4	AN6-45A	BOLT
8	AN960JD616	WASHER
4	MS21042L6	NUT (or MS21042-6)

REFERENCE ONLY

3.0 WEIGHT AND BALANCE:

INSTALLATION	WEIGHT	LONGITUDINAL	
		ARM	MOMENT
D412-666-011	1.90 lb 0.86 kg	163.0 in 4.14 m	310 in lb 3.56 m kg

4.0 PROCEDURE:

- 1) REMOVE AN6-12A BOLTS (4) ON INBOARD SIDE OF AFT SADDLE AND DISCARD. ON LANDING GEAR WITH DART AFT CROSSTUBES, REMOVE (4) AN6-40A BOLTS.
- 2) INSTALL D2888 LUGS WITH AN6-15A BOLTS (2) AS SHOWN IN FIGURE 1. USE AN6-45A (2) BOLTS ON DART CROSSTUBES, AS SHOWN IN FIGURE 2.
- 3) TORQUE BOLTS TO 95-110 in-lb (10.7-12.4 N-m).

5.0 NOTE:

IT IS ACCEPTABLE TO REPLACE THE AN6-15A/45A BOLTS WITH LONGER OR SHORTER AN6 BOLTS AS REQUIRED AND/OR INSTALL EXTRA AN960JD616 WASHERS UNDER NUT TO ENSURE 1.5 TO 4 THREADS IN SAFETY.




FIGURE 1
(BELL/AAI CROSSTUBES)




FIGURE 2
(DART CROSSTUBES)

C	- AN6-45A WAS AN6-43A, ADD NOTES - TO ENSURE COMPATIBILITY WITH D412-742-011/-013 - ESTIMATE (PARTS/PICK LIST) IS AFFECTED	MB	07.08.09
B	UPDATE KIT FOR BOTH SKIDTUBES AND COMPATIBILITY WITH DART CROSSTUBES	CP	02.03.04
A	NEW ISSUE	CP	99.05.03
REV.	DESCRIPTION	BY	DATE
DESIGN		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN			
CHECKED		DRAWING NO.	REV. C
MFG. APPR.	N/A	D412-666	SHEET 1 OF 1
APPROVED		TITLE	SCALE
DE APPR.		412 GROSS WEIGHT TOWING KIT	1:4
DATE	07.08.10	COPYRIGHT © 1999 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	